

METRO AUTO REBUILD SOUTH
3845 SO. WARNER AVE.
TACOMA, WA 98409
OFFICE: (253) 474-0736

*** PRELIMINARY ESTIMATE ***

RO# 31102

05/01/2012 02:55 PM

Owner

Owner: JET CHEVROLET
Contact: MIKE GATES
Address: 35700 ENCHANTED PKWY SOUTH
City State Zip: Federal Way, WA 98063
Work/Day: (253)952-8200
Cell: (253)318-4604
FAX: (253)874-7060

Inspection

Inspection Date: 05/01/2012 02:56 PM
Primary Impact: Non-Collision
Inspection Type:
Secondary Impact:
Company: Metro Auto Rebuild South
Contact: Keith Allison
Address: 3845 S. Warner St
City State Zip: Tacoma, WA 98409
Email: keith.allison@metroautorebuildsouth.com
Appraiser License # :
Work/Day: (253)474-0736
FAX: (253)474-1077

Repairer

Repairer: Metro Auto Rebuild South
Address: 3845 S. Warner St
City State Zip: Tacoma, WA 98409
Email: keith.allison@metroautorebuildsouth.com
License # :
Contact: Keith P Allison
Work/Day: (253)474-0736
FAX: (253)474-1077
Regulation ID: 601-883-134

Vehicle

2003 Ford Escape Limited 4 DR Wagon
6cyl Gasoline 3.0
4 Speed Automatic

Lic.Plate: 911ZPF
Lic Expire:
Prod Date:
Veh Insp# :
Condition: Good
Ext. Color: GOLD
Ext. Refinish: Two-Stage
Lic State: WA
VIN: 1FMCU941X3KA11472
Mileage: 111,197
Mileage Type: Actual
Code: P7103D
Int. Color: BEIGE
Int. Refinish: Two-Stage

Options

4-Wheel Drive	AM/FM In-dash CD Changer	Air Conditioning
Alarm System	Aluminum/Alloy Wheels	Anti-lock Brakes
Auto Locking Hubs (4WD)	Automatic Dimming Mirror	Bodyside Cladding
Center Console	Cruise Control	Dual Airbags
Electronic Transfer Case	Fender Flares	Fog Lights
Head Airbags	Heated Front Seats	Heated Power Mirrors
Intermittent Wipers	Keyless Entry System	Leather Seats
Leather Steering Wheel	Lighted Entry System	Mach Audio System
Overhead Console	Power Brakes	Power Door Locks
Power Drivers Seat	Power Steering	Power Windows
Privacy Glass	Rear Window Defroster	Rear Window Wiper/Washer
Reverse Sensing System	Roof/Luggage Rack	Side Airbags
Split Folding Rear Seat	Tachometer	Tilt Steering Wheel
Tinted Glass	Tonneau/Cargo Cover	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
1	I			Clean RF Seat Airbag Socket	Repair				1.0*	SM*
2	N			Diagnose & Clear SRS Fault	Additional Labor	\$95.00*				SM*
		2		Items						

Estimate Total & Entries

Other Parts	\$95.00
Parts & Material Total	\$95.00

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$50.00		1.0	1.0	\$50.00
Mech/Elec (ME)	\$56.00				
Frame (FR)	\$50.00				
Refinish (RF)	\$50.00				
Paint Materials	\$25.00				


Labor Total	1.0 Hours	\$50.00
Gross Total		\$145.00
Net Total		\$145.00

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 98409 Default
 Recycled Parts NOT REQUESTED

Audatex Estimating 6.0.353 ES 05/04/2012 04:28 PM REL 6.0.353 DT 01/01/2012
 Copyright (C) 2009 Audatex North America, Inc.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2009 Audatex North America, Inc.
 Audatex Estimating is a trademark of Audatex North America, Inc.